

# General Environmental Incident Summary

**Incident:** 3559      **Date/Time Notice:** 11/20/2014      1400      **DEM Incident No:**

**Responsible Party:** Sanjel

**Date Incident:** 11/20/2014      **Time Incident:** 0400      **Duration:**

**County:** Williams      **Twp:** 155      **Rng:** 101      **Sec:** 33      **Qtr:**

**Lat:** 48.20536      **Long:** -103.68600      **Method:** Interpolation from map

**Location Description:** Sanjel yard - 511 22nd Ave N.E Williston, ND

**Submitted By:** Alan Heltemes

**Affiliation:** HSE

**Address:** 511 22nd Ave NE

**City:** Williston

**State:** ND

**Zip:** 58801

## Received By:

**Contact Person:** Alan Heltemes  
511 22nd Ave NE  
Williston, ND 58801

**Distance Nearest Occupied Building:** 400 Feet

**Release Contained:** Yes

**Type of Incident:** Pump Leak

**Description of Released Contaminant:** Hydraulic fluid

**Volume Spilled:** 145.00 gallons

**Ag Related:** No

**EPA Extremely Hazardous Substance:** Unknown

**Reported to NRC:** Unknown

## Cause of Incident:

A hydraulic hose failed after starting the motor allowing the hydraulic oil in the tank to be pumped onto the frozen ground

## Risk Evaluation:

None

**# of Fatalities:** 0

**# of Injuries:** 0

**Affected Medium:** 03 - soil

## Potential Environmental Impacts:

None

## Action Taken or Planned:

Floor dry was placed onto the spilled fluid and a clean up company was called to remove the spilled product and remediate the area

**Wastes Disposal Location:** To be determined after laboratory testing is completed

## Agencies Involved:

## **Updates**

---

**Date:** 11/20/2014 **Status:** Reviewed - Follow-up Required

**Author:** Roberts, Kris

**Updated Volume:**

**Notes:**

Release due to pump leak from a truck. Followup is necessary to determine adequate cleanup.

---

**Date:** 12/4/2014 **Status:** Awaiting Documentation

**Author:** Martin, Russell

**Updated Volume:**

**Notes:**

12/4/2014 at 10:35, on location. Met with report contact. Leak occurred in truck parking area and flowed ~west/northwest for about 150 feet. Area was scraped by cleanup company (Mirror Environmental) about 1/2-3/4 inch deep according to contact. Walked site; there is no large visible staining underneath equipment at location. According to contact, rolloff containing impacted material was supposed to remain on site so that testing could be done before disposal, but rolloff was not visible at site. Contact called cleanup company, and cleanup company will determine location of the rolloff.

---

**Date:** 12/5/2014 **Status:** Correspondence

**Author:** Martin, Russell

**Updated Volume:**

**Notes:**

Email from report contact. Information concerning disposal of impacted material at Prairie Hills Disposal. Documentation included transfer and disposal receipts as well as sample analysis.